



# City of Marco Island Florida

51 Bald Eagle Drive  
Marco Island, Florida  
cityofmarcoisland.com

## Legislation Text

File #: ID 21-1843, Version: 1

Agenda Item: 8d.	Prepared By: Miguel Carballo, CFM, Manager
Business: Presentation	Department: Executive

Subject:

Presentation of court resurfacing options for the Marco Island Racquet Center clay tennis court number 8.

### BACKGROUND:

Marco Island Racquet Center clay tennis court number 8 is currently in need of getting resurfaced. This court has historically experienced issues with its Cal Cap underground irrigation system that is approximately 15 plus years old. This system is antiquated and is not recommended for new installations within the industry. The City has experienced several irrigation issues with this system on both courts 7 & 8, which can cause accelerated deterioration of the clay material over time.

There are nine (9) potential options available for the resurfacing of clay court #8:

#### Court 8 - Options

Option Number	Description	Cost + Inflation
1	Court Resurfacing	\$ 7,700.00
2	Court Resurfacing with New Subirrigation System	\$ 93,500.00
3	Court Resurfacing with New Above Ground Irrigation System (Including Resurfacing)	\$ 93,000.00
4-A	Replace with Hard Court - Tennis	\$ 40,700.00
4-B	Replace with Hard Cushioned Court - Tennis	\$ 55,000.00
5-A	Replace with Hard Court - Pickleball	\$ 40,700.00
5-B	Replace with Hard Cushioned Court - Pickleball	\$ 55,000.00
6-A	Replace with Hard Court - Mix Use	\$ 40,700.00
6-B	Replace with Hard Cushioned Court - Mix Use	\$ 55,000.00

**FUNDING SOURCE / FISCAL IMPACT:** Potential resurfacing option costs range from \$7,700.00 to \$93,000.00 depending on the option selected.

**RECOMMENDATION:** N/A

**POTENTIAL MOTION:** N/A